



### Above and Beyond Satisfaction

Turbine Engine Specialists is committed to achieving engine maintenance at the highest level of quality while meeting your critical flight schedule

### ANYTIME . . . ANYWHERE



**One Call And We're On The Way**

website: [tesservice.com](http://tesservice.com)

## Honeywell Authorized Heavy Service Center



- GTCP 36-100/150 Series APU's
- RE100 series APU's
- Improved compressor carbon seal and related components
- Dynamic group balance
- Test Cell
- Life limit component replacement
- AGB repair/rework

### Inventory

*With our large inventory and trained personnel we can respond to all your APU service needs.*

- Kits for routine inspections
- On site rental engine support
- Line replaceable units (LRU's)
  - GTCP 36-100/150 series APU's
  - RE100/220 series APU's
  - HTF7000
  - TFE731
  - CFE738

### HTF7000



### APU Services



### RE100 APU



### TFE731



### CFE738



### ATF3



## Services Provided

- 24/7/365 Emergency AOG service
- Off-site repair
- Expert troubleshooting
  - Download assistance 24/7
  - Phone troubleshooting support 24/7
- Engine R&R's
- LRU replacements
- Fleet management
- Honeywell authorized service center
  - GTCP 36-100/150 series APU's
  - RE100/220 series
  - Honeywell mobile major TFE731
  - HTF7000 series
  - CFE738
  - ATF3
- Expert staff trained by OEM's
- Fully licensed team dedicated to TOTAL customer satisfaction

website: [tesservice.com](http://tesservice.com)

## Contact Information

### Turbine Engine Specialists, Inc.

Meacham Field International Airport  
3804 Falcon Way West, Hangar 18S  
Fort Worth, Texas 76106

PHONE: 817-625-6100

FAX: 817-625-7080

WEBSITE: [tesservice.com](http://tesservice.com)

### MOE HATAMI

*President / General Manager*

Cell: (817) 401-9580

Email: [moe.hatami@tesservice.com](mailto:moe.hatami@tesservice.com)

### DAVE RASSETT

*Director of Sales & Great Lakes*

Cell: (214) 564-2182

Email: [david.rassett@tesservice.com](mailto:david.rassett@tesservice.com)

### THOMAS MEMERING

*Regional Engine Manager Southeast*

Cell: (859) 509-2129

Email: [tom.memering@tesservice.com](mailto:tom.memering@tesservice.com)

### DAN MOOG

*Regional Engine Manager Northeast*

Cell: (609) 744-8738

Email: [daniel.moog@tesservice.com](mailto:daniel.moog@tesservice.com)

### PATRICK ETIE

*Regional Engine Manager Southwest*

Cell: (817) 907-4375

Email: [patrick.etie@tesservice.com](mailto:patrick.etie@tesservice.com)

## HTF7000 Series



## FAA Licensed

Turbine Engine Specialists is an FAA Licensed Service Facility that specializes in Business Aviation Aircraft and Engines.

FAA Repair Station Certification TEHR262X

EASA Certification .145.6303

Bermuda Certification BDA/AMO/466

## Honeywell Authorized

We are a Honeywell Authorized Service Center performing maintenance on Business Aviation propulsion systems and APU's.

## Expert Crews

Turbine Engine Specialists is located in Fort Worth Texas at Meacham Field.

We have expert crews ready to deploy across the nation responding to both your scheduled and unscheduled aircraft and engine service needs, anytime... anywhere.

## Quality Service

Our technicians have over 175 years of combined experience to ensure quality service on your aircraft and engines.