



HTF7000 Engine Maintenance & Repair

Turbine Engine Specialists (TES) is a Honeywell Authorized Minor Service Center for the HTF7000 (AS907). Our factory trained and licensed technicians service MSP, Non-MSP, Warranty and JSSI customers 24x7 365 days a year.

HTF7000 Services Offered

- Worldwide Field Service
- Troubleshooting and Repair
- Removal and Reinstallation Capabilities (R&R)
- Rental and Exchange Units on site
- Pre-buy Inspections
- ECU Downloads
- Combustor Change
- 4000 / 8000 Borescope Inspections
- Compressor / Hot Section Repairs
- Fan-Vibration Analysis
- Acoustics

Engines Supported

- HTF7000
- HTF7250
- HTF7350
- HTF7500
- AS907-Series

Associated Airframes

- Challenger 300 / Challenger 350
- Citation Longitude
- Gulfstream G280
- Embraer Legacy 450/500
- Embraer Praetor 500/600

3900 Falcon Way West
Hangar 16S
Meacham Field
Fort Worth, Texas 76106

www.TESservice.com
817-625-6100
TES@TESservice.com